


BRASS DASHES



Labor-Saving Brass Leaders

(Hyphen or dotted) from 1 em to 18 ems Pica in length

	BODY	FACES	PER LB.
5 POINT			1.60
5½ POINT			1.60
6 POINT			1.60
7 POINT			1.60
8 POINT			1.60
9 POINT			1.50
10 POINT			1.50
11 POINT			1.40
12 POINT			1.40

When ordering, be particular to state the *style of leader* (whether *hyphen or dotted*), as well as the *face of the type* with which the leaders are to be used.

BRASS DASHES

184

No. 101. 50 cts.

No. 102. 50 cts.

No. 103. 50 cts.

No. 104. 50 cts.

No. 105. 50 cts.

No. 106. 60 cts.

No. 107. 60 cts.

No. 108. 60 cts.

No. 109. 60 cts.

No. 110. 60 cts.

No. 111. 60 cts.

No. 112. 60 cts.

No. 113. 70 cts.

No. 114. 70 cts.

No. 115. 70 cts.

No. 116. 70 cts.

No. 117. 70 cts.

No. 118. 70 cts.

No. 119. 70 cts.

No. 120. 70 cts.

No. 121. 70 cts.

Specimens of Larger Dashes furnished on application The Smaller Sizes cut to any length for news columns